

Micrometers with Small Measuring Faces

For measuring grooves, feather grooves, splines and other difficult to reach locations – Small measuring faces specially made to check precision workpieces.


Models MICROMASTER




| No | | |
|----------|----------|-----------|
| | mm | in |
| 06030034 | 0 ÷ 30 | 0 ÷ 1.2 |
| 06030035 | 30 ÷ 60 | 1.2 ÷ 2.3 |
| 06030036 | 60 ÷ 90 | 2.3 ÷ 3.5 |
| 06030037 | 90 ÷ 120 | 3.5 ÷ 4.7 |

Optional Accessory

| | |
|----------|---|
| 01961000 | 1 Lithium battery 3 V, 190 mAh, type CR 2032. For information on cables etc., see section A. |
|----------|---|



Models ISOMASTER AD



| No | |
|----------|---------|
| | mm |
| 00210101 | 0 ÷ 25 |
| 00210102 | 25 ÷ 50 |

